


REPAIR REPORT



Fluke Nederland B.V.
Science Park Eindhoven 5108
NL-5692 EC Son
CUSTOMER VAT REG. NO. : 

RMA: 

REPAIR INFORMATION:

MODEL: DTX-1800 INTL
SERIAL NUMBER: 
RECEIVE DATE: 

INCOMING STATUS:	Sub Function	Condition
Function/Info factory	None	Inoperative
All Functions		

COMMENTS:

REPAIR ACTION:
Board:
SMART - A1 MAIN

Ремонт печатной платы
удаленного модуля
Smart Remote

Reference:	Sympton:	Action:
U33	Damaged - electrical	Replaced
U18	Damaged - electrical	Replaced
U41	Damaged - electrical	Replaced
U32	Damaged - electrical	Replaced
U39	Damaged - electrical	Replaced
U36	Damaged - electrical	Replaced
U2	Damaged - electrical	Replaced
U91	Damaged - electrical	Replaced

Board:

Reference:	Sympton:	Action:
------------	----------	---------

TECHNICIAN: SHOEVENS